



OVERVIEW


CONTENTS

1




2



1)




2)



\* SCHROEVEN NIET MEEGELEVERD - LES VIS NE SONT PAS INCLUS - SCHRAUBEN NICHT MITGELIEFERT - SCREWS NOT INCLUDED  
 \*\* DEURDIKTE - LARGEUR DE LA PORTE - TÜRDICKE - DOOR THICKNESS



### ADJUSTMENTS



\* SCHROEVEN NIET MEEGELEVERD - LES VIS NE SONT PAS INCLUS - SCHRAUBEN NICHT MITGELIEFERT - SCREWS NOT INCLUDED